


2X2 type of tiles

vs. UNITY'S Self-Interlocking



- Lack of a sufficient self-interlocking system that would require an accessory item, such as fasteners, pins, clips, blocks to create a “false” interlock, may result in:
  - Product-To-Product = Separation, curling and peeling which may result in trip hazards and vandalism.
  - Appearance issues that may attract unwanted attention from safety inspectors
  - Trip Hazards / Injuries from normal everyday use
  - Unwanted debris building up on the edges or underneath that would create other “potential” problems
  - May promote higher injuries/insurance premiums due to the lack of quality manufacturing