


Test Results For Fall Safety Heights

G-MAX & HIC test results conducted at an independent testing laboratory per ASTM F-1292-09, F-355 Procedure C (ANSI Head-Form C), **PASSED**.



Weathering (Aging) Test

Test results conducted at an independent laboratory per ASTM C-67, & ASTM D-573, **PASSED**

Skid Resistance Test

Test results conducted at an independent laboratory per ASTM E-303, **PASSED**

Fire Retardant Test

Test results conducted at an independent laboratory per ASTM E-108 & E-648, **PASSED**

Thermal Conductivity (R-Value)

Test results conducted at an independent laboratory per ASTM C-518-98, **PASSED**

Reflectance/SRI & Emmittance Test

Testing conduction at an independent laboratory per ASTM E-903, E-891 and E-1980..... **VARIES**

Wind-Uplift Test

Test conducted at an independent laboratory per ANSI 4474 & ASTM D3161. **PASSED**

Impact Resistance Test

Test conducted at an independent laboratory per UL 2218, Class 4. **PASSED**